

Date	May 20th 2013
Object	Safety Warning 2013/04 WALIBI LITE, WALIBI ² , EVASION ²

Replacing reserve parachute pocket elasicated cords

Why this warning ?

The reserve parachute pocket elasicated cords could become weakened by the stitched line holding them in place. To avoid and prevent any premature wear- ing and risk of tearing of the aforementioned elasicated parts, we will suggest you to replace them by the cords included with this correspondence.

Which products are concerned

All 2013 tandem pilots harness from January to May 17th 2013
 WALIBI LITE : code A1 out of A3
 WALIBI 2 : code A1 and A2
 EVASION 2 : code A1

How to recognize my harness's code ?

The code is found on the sewn label located under the right shoulder flap reserve parachute connection point.

Label location



code location



Replacement set :



Date	May 20th 2013
Object	Safety Warning 2013/04 WALIBI LITE, WALIBI ² , EVASION ²

Replacing elasicated cords

