

| | |
|-----------------|--------------------|
| Publishing date | 28/10/2019 |
| Document number | SUPAIR_2019_10_001 |
| Page number | 1/1 |



SAFETY WARNING

SUBJECT : ALTIRANDO Lite
Parachute pocket

STATUS :

- LOW
- MEDIUM
- CRITICAL

Nature of the problem :

We have identified that, on some ALTIRANDO Lite harnesses, when using certain parachutes (high volume mostly), the magnetic flap used to fasten the parachute pocket could too easily get out of its socket.

The handle can therefore break lose and the parachute pocket may inopportunately open.



Product in question : ALTIRANDO LITE harnesses (A1)

Procedure to follow : Thoroughly examine the magnetic flap as shown below

A : The magnetic flap regularly get out of its socket



Contact SUPAIR (info@supair.com)

To order a flap extension, free of charge. To put it on, slide this piece of fabric directly on the flap (as shown in the pictures below).

B : The magnetic flap stays in its socket



 No problem
Safe flights !

