

<b>Published date</b>	16/06/2017
<b>Document number</b>	SUPAIR_2017/06_001
<b>Page number</b>	1 / 2



# SAFETY WARNING

## SUBJECT: STRIKE Harness

Tear in leg strap side panels

PRIORITY  
STATUS

LOW

MEDIUM

CRITICAL

### Problem description :

It is possible that tears could appear in the side panels when high G force is applied




### Concerned products :

#### STRIKE ind A1


(Production up to April 2017 included)



Open the back storage compartment  
The production index is on the small label



Recto




Verso

### Facts/ Ascertainment :

Some tears occurred in the side panel during hard spiral dives or other manoeuvres with high G force. The tears do not compromise the structure of the harness but may destabilise the pilot in the harness during and after the manoeuvre and the harness might become uncomfortable to fly.

<b>Published date</b>	16/06/2017
<b>Document number</b>	SUPAIR_2017/06_001
<b>Page number</b>	2 / 2

## Procedure to follow :



## Person able to perform the harness :



## Person able to conduct the repairs :



*Except if professional repair is necessary.*

**DELAIS :** **The inspection must be done immediately**

## Documents recipients :



Safety Warning : SUPAIR\_2017/06\_001